



INSPECTION REPORT

Report No.:

INSPECTION INFORMATION

Client			
Supplier	Chineti Group Limited		
Factory			
P.O. No.		Inspection standard	ISO2859
Item No.		Sampling Plan	Single,Normal
Product Description	Parking lot related products	Inspection Level	Fixed Sample
Inspection instruction	GWI-H-044-YSD	AQL	Critical
Inspection Date	Jan 16-17 th , 2026		Major
Inspection Location	Qingdao,Shandong,China		Minor

INSPECTION RESULT SUMMARY

Project	Conclusion			Overall Conclusion
1. Quantity	<input checked="" type="checkbox"/> PASS	<input type="checkbox"/> Not Conform	<input type="checkbox"/> Pending	<input checked="" type="checkbox"/> PASS <input type="checkbox"/> Not Conform <input type="checkbox"/> Pending
2. Workmanship	<input checked="" type="checkbox"/> PASS	<input type="checkbox"/> Not Conform	<input type="checkbox"/> Pending	
3. Style, Color & Documentation	<input checked="" type="checkbox"/> PASS	<input type="checkbox"/> Not Conform	<input type="checkbox"/> Pending	
4. Field Test & Measurement	<input checked="" type="checkbox"/> PASS	<input type="checkbox"/> Not Conform	<input type="checkbox"/> Pending	

SPECIAL ATTENTION POINT

1	Quantity	NIL
1.1	Upon arrived thefactory, the bulk goods have 100% finished and packed.	
2	Workmanship	NIL
2.1	Refer to table 2.	
3	Style, Color & Documentation	NIL
3.1	No approved sample for reference.	
3.2	No packaging & shipping mark data were provided for reference. Please refer to attached packaging and product photos for details.	
4	Field Test & Measurement	NIL
4.1	No calibration certificate of weight scale/steel ruler was available. The result of weight checked only for reference.	
4.2	The factory has not provided any product testing reports.	
4.3	For Item MU120105 function test on site.	

1. Quantity						PASS
Item No.	P.O. QTY	Shipment QTY	PCS/CTN	Packed QTY	Unpacked QTY	Sample Size
		PCS CTNS				Packed Unpack



Factory gate



Goods stack



Goods stack



Goods stack




Product line



Product line

	
Product packing view	Product packing view
	
Product packing view	Sticker on packing
	
Packing size check	Packing size check





Function test




Function test



Power packing view



Shipping mark



Sticker on carton



Open carton